

Worried about Refilling of *Canon CLI-8 and PGI-5* ???

Not anymore, Because...

TRACK
Engineers

&




INDIGO

Introduce

“Complete Solution for Refilling Canon CLI-8 and PGI-5”
New

Fixtures, Chip Resetters, Inks and Sealing Caps



Refill Fixtures :

- ❖ Simple to Use, Just push-pull to fill
- ❖ No Drilling Required
- ❖ Very Fast
- ❖ Maintains Refillability
- ❖ Different Fixtures for CLI-8 & PGI-5




Canon Chip Resetter :

Resets chips for CLI-8 and PGI-5

Excellent quality Formujet[®] inks

INK	Best suited for Cartridge No	Available Packaging
ICC-06 Color- C/Y/M/PM/PC/R/G	Canon CLI-8 /BCI6 / BCI-3/ PG 52	200 gm (each color) 1 Kg (each color)
ICB PG-40 (black)	PGI-5 & PG 40/50	200 gm 1 Kg





Sealing caps:

To avoid Leakage after refilling

The CLI-8 and PGI-5 cartridges are compatible with following printers:

- Canon PIXMA iP4200 Canon PIXMA iP4300
- Canon PIXMA iP4500 Canon PIXMA iP5200
- Canon PIXMA iP5200R Canon PIXMA iP6600D
- Canon PIXMA iP6700D Canon PIXMA MP500
- Canon PIXMA MP530 Canon PIXMA MP600
- Canon PIXMA Mp610 Canon PIXMA MP800
- Canon PIXMA MP800R Canon PIXMA MP810
- Canon PIXMA MP830 Canon PIXMA MP950
- Canon PIXMA MP960 Canon PIXMA Mp970
- Canon PIXMA MX850 Canon PIXMA Pro9000



So order now :

TRACK
Engineers

209, Devendra Industrial Estate, Lokmanya Nagar, Pada No. 2, Thane (West) - 400 606. Mumbai (INDIA).
Phone : +91-22- 25882125 / 2588 1080 Fax : -91-22-2588 3582
Email : track100@rediffmail.com / trackeng@gmail.com Website : www.trackengineers.com



INDIGO IMAGING SUPPLIES

NO.33, Nahur Udyog Premises, Near P.T.Colony,
Mulund (W), Mumbai - 80
Ph : - 022-25641503/25620583
Email :- track44@gmail.com